

City of Baltimore Wet Weather Consent Decree Smoke and Dyed Water Testing Form	Page 1 of 3
---	-------------

Page 1 of 3

Sewershed : Gwynn Falls

Company : URS

Date : 09/23/2008

Test to be Performed : Smoke : <u>X</u> Dyed Water : <u> </u>
--

Ground Condition :
Dry : X Damp : Wet :


Supervisor : <u>Ryan Lamont</u>
--

Manhole ID : S03QQ_004MH

Test ID : S1032-022030

Notifications (Residents, Fire, 311) : <u>Yes</u>

Field Sketch : (Show All Manholes with Numbers, Blower Placement Location, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photograph Numbers)



City of Baltimore Wet Weather Consent Decree Smoke and Dyed Water Testing Form

Page 2 of 3

Sewershed : Gwynn Falls

Company : URS

Date : 09/23/2008

Test to be Performed :
Smoke : X Dyed Water :

Ground Condition :
Dry : X Damp : Wet :

Supervisor : Ryan Lamont


Manhole ID : S03QQ 004MH

Test ID : S1032-022030

Notifications (Residents, Fire, 311) :
Yes

Field Sketch : (Show All Manholes with Numbers, Blower Placement Location, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photograph Numbers)

ID



Location: N/A; Type: Cleanout; Smoke: Heavy; Status: Private Property


Landscape



Defect



ID



Location: N/A; Type: Service Lateral; Smoke: Medium; Status: Private Property

Landscape



Defect



City of Baltimore Wet Weather Consent Decree Smoke and Dyed Water Testing Form

Page 3 of 3

Sewershed : Gwynn Falls

Company : URS

Date : 09/23/2008

Test to be Performed :
Smoke : X Dyed Water :

Ground Condition :
Dry : X Damp : Wet :

Supervisor : Ryan Lamont


Manhole ID : S03QQ 004MH

Test ID : S1032-022030

Notifications (Residents, Fire, 311) :
Yes

Field Sketch : (Show All Manholes with Numbers, Blower Placement Location, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photograph Numbers)

ID



Location: N/A; Type: Service Lateral; Smoke: Medium; Status: Private Property


Landscape



Defect




ID



Location: N/A; Type: Service Lateral; Smoke: Medium; Status: Public ROW

Landscape



Defect

